EXECUTIVE SUMMARY



Capacity	/ Assessment				
Design C	Capacity:	345			Percent Occupied: 93%
Function	nal Capacity:	293			reiteilt Occupied. 93%
	Enrollment	272			85% Capacity is assumed full
	Constructed : 1952, Addition				
Building	Current Square Footage: 4	1,449			
Assessm	ent Grading	1-Pass		5- Fail	
	Scale	: 1 2	3 4	5 1	Note: Score over 3 recommend replacement
Site	Parking and Drives				Concrete parking, and asphalt drive
	Sidewalks				Minimal sidewalks, none connect to doors, not accessible.
	Landscape/Irrigation				Several ponding water locations
	Play Grounds				Play area in fair condition. Not accessible.
	ADA Accessibility				Non-compliant entry ramp & site circulation . No HC parking
	Utilities& Drainage				Ponding water in multiple areas
	Site Lighting				Non-uniform lighting at firelane, Minimal lighting typ.
Futanian	Security Exterior Walls	+ + -		_	No fencing around site. No security vestibule at entry
Exterior	Structure/Foundation			_	no weepholes in brick @ some locs. Brick control joints pulling apart No visible cracks on exterior, no foundation settling noticeable
	Windows				Deteriorating condition. Clouded glazing & mildewy sealant @ some
	Doors/Entrances			_	Fair
	Roofing			_	Single ply is in poor condition and should be replaced
	Weather/Waterproofing				Poor and needing maintenance.
	Canopies				Some damage on posts, conduits running on surface of canopies
Interior	TEA Compliance	+ + -			come damage on pools, conduits ramining on sample or carregies
	Educational Adequacy			+	Educational Adequacy Fair. No specialized rooms.
	Finishes			_	Mostly acoustic ceiling tiles (ACT), no evidence of roof leaks
	Restrooms				Student restrooms in fair condition, not accessible.
	Food Service				Contains both functional & outdated equipment. Showing wear.
	Doors/Hardware			\	Nood doors/frames and hollow metal frames. HW not compliant.
	Accessibility			\	Nater fntain, classroom sinks/RR, most door hardwarenot ADA
	ACM materials			A	ACM present.
	Code requirements			l	Jnknown building code used.
MEP	Mechanical				
	Units			$\overline{}$	Roof mtd. Fans appear to be original & recommend replacement
	Ductwork	\vdash			AHUs and control valves in poor condition
	Exhaust			1	Not all "exhaust" were running & is locally controlled by wall switch
	Electrical				
	Building service Panels				Pole mounted transformers provided Replace eqpmt. Replacement parts more expensive than new gear.
	Distribution				N/A
	Plumbing			,	γ <u>ν</u>
	Infrastructure			F	Replace galvanized pipe with copper. Some corrosion @ existing
	Fixtures			$\overline{}$	Jpgrade will be req'd if major work occurs within building
	Life Safety Systems				
	Fire Sprinkler			E	Building is not sprinklered.
	Fire Alarm			_	Fair condition.
	Emergency Lighting			E	Battery pack Itng installed randomly. Install generator & emerg. Ltng.
	Exit Signage			F	Recommend upgrade w/ installation of emergency ltng system
	Technology				
	Data			1	Adequate teacher/student computer drops
	Wi Fi			1	es.

Total Score - 3.68

EXECUTIVE SUMMARY



OVERALL SUMMARY & RECOMMENDATION

Stephen F. Austin Elementary is over 60 years old and most systems require upgrade or replacement. Accessibility and security is lacking throughout the school. There are several ADA compliance issues, including restroom areas. The building's mechanical and electrical systems are in need of replacement. The life safety system is in need of upgrading. The site parking, roads, site access and handicapped compliant access to the play areas are non compliant. The security of the site at the main entry and multiple classroom wings provide uncontrolled points of entry that compromise the security of the facility.

RECOMMENDATION: The lack of security can be easily addressed with perimeter fencing. Most MEP systems and life safety systems require replacement. Non-accessible items, such as the student restrooms and playgrounds, should be brought into compliance with the current accessibility code. The roofing systems requires replacement. Interior finishes require ongoing maintenance.

EDUCATION ADEQUACY ASSESSMENT

1= Excellent 3= Fair 5= Failure 2= Good 4= Poor

		Maintenance Cycle	e Condition			Special Notes			
	Schedul				or				or
		Years		Quality			Observations		
			1	2	3	4	5	N/A	
_	CATION ADEQUACY								Educational Adequacy Fair. No specialized rooms.
Clas	sroom Educational Adequacy								
_	Power								
_	Technology								
_	Classroom size								
	Marker board/ tack board								
Spe	cial Education Classroom								
_	Rooms					_			
_	Restrooms								
_	Accessibility								
	Showers								
Scie	nce Room								No Science Labs
	Air Exchanges								
_	Demo tables								
_	Sink								
_	Eye wash								
-	Fire Blanket								
-	Showers								
-	Utility shut off								
-	Fume hood								· ·
-	Prep rooms								-
Med	a Center								
	Technology								-
-	Reading area								-
-	Power								
Athle	etic Facilities								-
	Outdoor courts								
-	Outdoor fields								
-	Playgrounds								
-	Gymnasium					_			Gym and Cafeteria are the same space.
-	Locker rooms		-		_				- Sym and Saletena are the same space.
Com	puter Facilities		-					_	-
3011			$\vdash \vdash$	_					
_	Technology		\sqcup						
_	Room size								
	Electrical & Data								
-									


EDUCATION ADEQUACY ASSESSMENT					
		1= Ex	cellent		2= Good
		3=	Fair		4= Poor
		5= F	ailure		
	Maintenance Cycle		Conditio	n	Special Notes
	Schedule		or		or
	Years		Quality		Observations
Art Facilities					
Kiln/ kiln vent	_				
Demo table					
Vocational Rooms					School would like to offer Robotics, but inadequate space.
Demo tables	_				
Sink					
Eye wash					
Power					
Technology					

Building Capacity Analysis

Rm No.	Room Name	Function		Area	Meets TEA	Design Capacity	Functional Capacity (85% D.C.)
						<i>J</i> , ,	
103	Classroom	Classroom	Kindergarten	762	N	21	
104	Classroom	Classroom	1st Grade	762	N	21	
105	Classroom	Classroom	Kindergarten	762	N	21	
106	Classroom	Classroom	Intervention	762	Υ	NA	
107	Classroom	Classroom	2nd Grade	762	Υ	22	
108	Classroom	Classroom	Intervention	762	Υ	NA	
109	Classroom	Classroom	2nd Grade	762	Υ	22	
110	Classroom	Classroom	Pre-Kindergarten	762	N	21	
111	Classroom	Classroom	Intervention	719	Υ	NA	
112	Classroom	Classroom	3rd Grade	719	Υ	22	
113	Computer Lab	Computer Lab	Computer Lab	719	N	19	
114	Classroom	Classroom	3rd Grade	719	Υ	22	
115	Classroom	Classroom	4th Grade	719	Υ	22	
116	Computer Lab	Computer Lab	Computer Lab	719	N	19	
117	Classroom	Classroom	4th Grade	719	Υ	22	
118	ISS / After school program	Classroom	Ace	719	Υ	NA	
125	Storage	Storage	Storage	204	NA	NA	
126	Parent	Parent Room	Admin Office	196	NA	NA	
127	Speech / Dialogue	Classroom	Speech Pathologist	196	N	NA	
131	Music	Classroom	Music	881	Υ	NA	
132	Classroom	Classroom	Elective Classroom	881	Υ	NA	
133	Classroom	Classroom	6th Grade	902	Υ	25	
134	Classroom	Classroom	5th Grade	678	N	21	
135	Classroom	Classroom	6th Grade	672	N	24	
136	Classroom	Classroom	5th Grade	672	N	21	
Library	Library	Library	Library 1	3012	Υ	NA	
Cafetorium	Gym	Gym / Café	Gym ES	3288	Υ	NA	
	Total Capacity					345	293


Site Plan





Floor Plans







401 N. GULF BLVD.

FREEPORT, TX 77541

SITE INFORMATION

Current # of Parking Spaces: 16

Parent drop-off/pick-up Inadequate.

Bus drop-off/pick-up Inadequate.



	General Notes:
Site Conditions	
Parking & Drives	Concrete parking, and asphalt drive
Sidewalks	Minimal sidewalks, none connect to doors,not accessible.
ADA Accessibility	Non-compliant entry ramp & site circulation . No HC parking
Site Signage	No directional site signage. HC sign at parking. Marquee
Playground Areas	
Condition	Play area in fair condition. Not accessible.
Accessibility	Not accessible, needs ramp
Athletic Areas	Basketball court in fair condition, minimal cracks, damaged
Landscaping/Irrigation	Several ponding water locations
Utilities & Drainage	Ponding water in multiple areas
Dumpster Service Area	within staff parking lot. Not screened.
Site Lighting	Non-uniform lighting at firelane, Minimal lighting typ.
Security	No fencing around site. No security vestibule at entry
Chain Link Fencing	No overall site fencing. Req'd for site security
Ornamental Fencing	No fencing. Req'd for site security

The information contained in this document comes from a range of sources in a limited time frame and may not be completely reliable. The intent of this survey is to obtain a general sense of the overall condition of the subject property and to identify particular areas or systems that may require more in-depth and verifiable study.

						, ,	
	Maintenance Cycle	1	Condition			Special Notes	
	Schedule		or			or	
	Years		Qua	-,			Observations
Site work		1	2 3	4	5	N/A	
On-Site Utilities & Drainage							Ponding water in multiple areas
Site Drainage / Erosion Control							Ponding water, bar ditch at entry for drainage
Storm Sewer Line							<u> </u>
Sanitary Sewer Line							
Water Supply Line / Sprinkler Supply Line							
Gas Line							Exposed gas line
Electric Service Line / Phone Line							low hung power lines
Site Lighting- Building and Parking Lots							Site lighting uneven across drive/parking, canopy lights exist
Exterior Concrete Pads & Pavement- Around building , mechanical yards							Entry paving is good, asphalt road, concrete parking/fire lane
Fire Hydrants / Utility Vaults / Misc.							
Landscape & Irrigation							Several ponding water locations
Topsoil and finished grading condition							
Grass and Sod condition	-						
Trees / Plants / Shrubs / Ground Cover / Vines							Trees overhang fire lane and roof
Landscape Maintenance				T			Grasses growing in gutters, not maintained
Site Irrigation System			-		干		
	· 	\vdash	_		+	H	
Site Parking & Drives							Concrete parking, and asphalt drive
Roads / Drives / Parking Areas		П	\top	Т			Cracking/decomp asphalt and water ponding @ staff parking.
Fire Lanes			+	П	_		Concrete fire lane. Non-uniform lighting around fire lane
Parking lot and fire lane stripping		\vdash	+	Ë			Parking striping Illegible
Traffic - Parking Control / Misc. Site Equipment		\vdash	+		10		Inadequate visitor parking, all parallel spots
Curbs		\vdash	-		۳		Poured-in-place curb on 1 side of drive, vehicle stop on other side
Curbs	· ———	\vdash	ᆛ	_		+	1 oured-in-place curb on 1 side of drive, verificie stop on other side
							Minimal side wells, were connect to do so not connected
Sidewalks		_	_	1-			Minimal sidewalks, none connect to doors,not accessible.
Sidewalks / Steps / Ramps		\vdash	_		-	_	Cracking, uneven sidewalks.
Court Yards / Patios / Misc. Paving							-
							B. L. H. H
Outdoor Athletic Areas				_			Basketball court in fair condition, minimal cracks, damaged goals
Play Fields		$\perp \perp$			_	_	Asphalt running track with some ponding
Tennis Courts							
Hard court play areas							1/2" offset around paving not accessible. Minimal cracking
Backstops							Basketball backboards cracking w/poles in fair condition
						Ш	
Playgrounds							Play area in fair condition. Not accessible.
Play areas						Ш	Open playground
Playground access for handicapped				1		Ш	Not accessible, needs ramp
Playground equipment						Ш	
Playground base material] _			Decomposed mulch with grass growing. Base lining decomposing.

EXISTING SITE ASSESSMENT FORM

The information contained in this document comes from a range of sources in a limited time frame and may not be completely reliable. The intent of this survey is to obtain a general sense of the overall condition of the subject property and to identify particular areas or systems that may require more in-depth and verifiable study.

	Maintenance Cycle Condition			Special Notes			
	Schedule	Schedule or			or		
	Years		Qualit	у			Observations
Miscellaneous Exterior Site Items							
Site Lighting							n-uniform lighting at firelane, Minimal lighting typ.
Site Security						No	fencing around site. No security vestibule at entry
Cameras						Nor	ne evident.
Chain Link Fencing / Gates						No	overall site fencing. Req'd for site security
Ornamental Fencing / Gates						No	fencing. Req'd for site security
Misc. Structures							
Site Walls -Retaining / Screen					[No	retaining/screen walls.
Dumpster Service Area						with	hin staff parking lot. Not screened.
Site Signage- Directional / Handicapped						No	directional site signage. HC sign at parking. Marquee sign good.
Site Furniture / Specialties						Rus	sting and bent picnic tables
Misc. Site work / Recreational / Site Structures					[
ADA Compliance/Accessibility						Nor	n-compliant entry ramp & site circulation . No HC parking
Compliant Sidewalks/Curbs						Not	t compliant. Sidewalks do not extend to doors.
Compliant Ramps & Handrails						No	ramps on property.
HC & Van Accessible Parking Spaces						No	handicapped accessible parking
Accessible routes from HC parking, Bus drop off & mass transit to front door						Nor	ne available
			Ш				
Average Site Grade:						4	



401 N. GULF BLVD. FREEPORT, TX 77541

EXTERIOR BUILDING INFORMATION

Exterior Building Cladding

Materials:

Single wythe masonry, CMU infill

Roof Type: Single-ply

Single pane double hung aluminum

Exterior Window Materials: Single pa

frame windows



	General Notes:
Exterior Building Condition	
Exterior Envelope	
Wall Condition	no weepholes in brick @ some locs. Brick control joints pulling apart
Window Condition	Deteriorating condition. Clouded glazing & mildewy sealant
Doors/Entrances	Fair
Secure Entrance	No security vestibule
Farradation /Streeture	No visible cracks on exterior, no foundation settling
Foundation/Structure	noticeable
Roofing Areas	Single ply is in poor condition and should be replaced
Existing Warranty	No warranties remaining
Area for repair	None
Area for Replacement	All single ply areas
Exterior Building	Sitelighting uneven at firelane, Minimal lighting in parking
Lighting	areas
Kitchen dock/loading	4" paving at delivery entrance, 3" bump in concrete not
entry	ideal for deliv.
Comonico	Some damage on posts, conduits running on surface of
Canopies	canopies
Additional information	Moldy, warped exterior building fascia at perimeter of
Additional information	building.
	<u></u>

EXISTING EXTERIOR BUILDING ASSESSMENT FORM


The information contained in this document comes from a range of sources in a limited time frame and may not be completely reliable. The intent of this survey is to obtain a general sense of the overall condition of the subject property and to identify particular areas or systems that may require more in-depth and verifiable study.

		_					
	Maintenance Cycle	cle Condition					Special Notes
	Schedule						ОГ
	Years		Qua				Observations
Building Structure/Foundation	· ·	1 :	2 3	_	5	N/A	No visible cracks on exterior, no foundation settling noticeable
Foundation							
Piers / Caissons / Piles / Footings							
Grade Beams							Cracking in concrete grade beam evident at Building Addition
Foundation Walls							
Special Foundation / Misc.							
Substructure - Slab - on - Grade							
Basement / Below Grade Exterior Walls	_						
Interior Slab on Grade							Uneven floor slab at Library entry (1979 Addition)
Entry Steps / Ramp / Porch Slabs							Cracking at entry slab
Sub-base - For All Bldg. Slabs							
Special Substructure / Misc.							
Superstructure							
Suspended Floor / Mezzanine / Roof / Column Systems							
Interior Structural / Shear Walls	-						
Fireproofing				1			Unknown if present on structure.
Structural Steel							
Misc. Steel			1				
Concrete frame under super structure							
Pre-Engineered Metal building							Rusting & damaged walls/roof at exterior mech. room
Stairs & Miscellaneous structures							
Stairs & Ramp Structures	-						
Platform & Catwalk Structures							
Misc. Attached Structures -Canopy / Porch / Rooftop							Bent canopy columns at entry. Rusting canopy roof deck
Misc. Steel -Structural Framing / Bracing			1				
Misc. Wood -Blocking / Framing / Rough Carpentry -Exterior			1				
Expansion Joints			1				
Building Exterior Shell	T	h	1	1	Ħ	\neg	
Roofing							Single ply is in poor condition and should be replaced
Roof Covering							Single ply is in poor condition and should be replaced
Traffic / Pavement Toppings							Single ply is in poor condition and should be replaced
Roof Insulation & Fill							Insultion values do not meet current code requirements
Roofing Sheet Metal	-						Sheet metal needs to be replaced
Skylights	-						
Roof Openings / Misc.	-						Roof Penentrations need to be addressed at the time of replacement
Misc. Wall & Roof Trim	-						<u> </u>
Warranty							No warranties remaining
							-

EXISTING EXTERIOR BUILDING ASSESSMENT FORM

The information contained in this document comes from a range of sources in a limited time frame and may not be completely reliable. The intent of this survey is to obtain a general sense of the overall condition of the subject property and to identify particular areas or systems that may require more in-depth and verifiable study.

	Maintenance Cycle	Maintenance Cycle Condition		Special Notes	
	Schedule	or			or
	Years	Quality			Observations
Exterior Walls	100.0	Ĭ	uunty		no weepholes in brick @ some locs. Brick control joints pulling apart
Exterior Wall Face & Back-Up Construction- Brick				Т	Weep holes missing at some brick. Control its pulling apart.
Exterior Wall Face & Back-Up Construction- Plaster					
Exterior Load Bearing Walls					
Exterior Balcony Walls / Railings					
Exterior Louvers / Sunscreens					
Exterior Painting			[3	CMU Walls uniformly painted. Peeling paint at soffits/fascias.
Windows/Glazed Walls					Deteriorating condition. Clouded glazing & mildewy sealant @ some
Windows					Single hung aluminum casement, single pane windows
Curtain Walls					
Exterior Doors	·				Fair
Exterior Storefront / Entry Walls			[]	
Exterior Storefront / Entry Doors			[]	Wiring visible at top of entry doors (at interior)
Exterior Doors					Interior door used for exterior condition at gym exit.
Exterior Overhead / Rolling Doors					
Exterior Hardware			0		
Exterior Door Panic Hardware					
Weather/Waterproofing					Poor and needing maintenance.
Waterproofing					No evidence of leaking from interior of building.
Caulking / Sealants				1	Brick control joint caulking falling out. Mildewy sealant @ windows
Exterior Soffits					Unevenly painted. Mildew and Peeling paint at fascias
Finishes To Misc. Exterior Structures					Adequately sealed at connection bet. canopies & building
Miscellaneous Exterior Building Items					
Canopies					Some damage on posts, conduits running on surface of canopies
Freestanding Canopies				_	Some rusting at canopy deck. Bent supports @ canopy at entry drive
Canopies attached to building					
Exterior Building Lighting			E	_	Sitelighting uneven at firelane, Minimal lighting in parking areas
Secure Front Entry					No security vestibule
Kitchen Dock/Loading Zones		+]	4" paving at delivery entrance, 3" bump in concrete not ideal for deliv.
Average Exterior Grade:		\dashv			4
go =Accof Orago.		1 1			·




401 N. GULF BLVD. FREEPORT, TX 77541

INTERIOR BUILDING AREAS	
Circulation:	No security vestibule at entry.
Interior signage:	Signage at classrooms and restrooms.
	ADA compliant.
Layout:	Double loaded corridors. 5th, 6th, and Art/Music are located separately from main building.



	General Notes:
Interior Building Areas	
Classrooms	Double-loaded corridors. Shared restrooms between classrooms.
SPED Classrooms	Not a specialized classroom and Not accessible.
Science Labs	No Science Labs present.
Computer Labs	2 computer labs. Area does not meet TEA standards. Some computers located w/i Classrms
Art/Music	Classrooms located in satellite buildings.
Library	Inadequate space for reading & presentations. There is no place to put presentation screen.
Cafeteria	Serves as Cafeteria and Gym with stage, folding tables
Kitchen/Serving	Not accessible, tables in cafet. for condiments
Gymnasium	Serves as Gym and Cafeteria with stage
Auditorium	Shares space with Gym and cafeteria
Administration	Limited circulation for visitor check-in.
Staff Work Areas	Limited circulation.
Clinic	



401 N. GULF BLVD. FREEPORT, TX 77541

INTERIOR FINISH INFORMATION

Flooring Types: Carpet & vinyl comp.tile (VCT)

Walls: Brick or CMU with painted finish

Ceilings: Acoustic ceiling tiles (ACT)



	General Notes:
Interior Building Cond	ition
Ceilings	Fair Overall Condition
Floors	VCT & carpet. Some VCT pulling apart (possible slab heaving)
Interior Wall	VCT & carpet floors, CMU & gyp bd wall finish, ACT on
Finishes	ceiling.
Millwork	Mostly wood w/plastic laminate(PLAM) and is chipping or cracked.
Restrooms	Student restrooms in fair condition, not accessible.
Food Service Areas	Contains both functional & outdated equipment. Showing wear.
Doors and	Wood doors/frames and hollow metal frames. HW not
Hardware	compliant.
ADA Compliance	Water fntain, classroom sinks/RR, most door hardware-not ADA

EXISTING INTERIOR FINISHES ASSESSMENT FORM

1= Excellent 3= Fair

3= Fair 5= Failure 2= Good

4= Poor

	Maintenance Cycle	Conc	lition		Special Notes
	Schedule	0	r		or
	Years	Qua			Observations
nterior Building Conditions		1 2 3	3 4	5 N/A	
Interior Building Finishes					Mostly acoustic ceiling tiles (ACT), no evidence of roof leaks
Ceilings				\bot	Fair Overall Condition
Acoustical Ceilings					Main act ceiling installed below original 12x12 ACT glued to furring
Ceiling Grid Condition				\bot	90 degree grid, fair condition
2 x4 or 2 x 2 tiles - condition and type			١	\bot	2x4 and 2x2 acoustic foam
Vinyl Coated or Other type installed in grid system					
Plaster Ceilings					
Drywall Ceiling			١		
Metal Ceilings					
Exposed / Painted Ceilings					
Soffit / Bulkhead Walls					
Special Ceilings / Soundproofing / Misc.					
Floors			1		VCT & carpet. Some VCT pulling apart (possible slab heaving)
Carpeting			1		Mostly in fair condition, needs minor treatment (6' wide rolled)
Resilient Flooring - VCT					Some areas are pitted, some fair VCT. Some pulling apart of tiles
Pavers / Slate / Marble					
Quarry Tile					
Ceramic Tile					Ceramic tile at shared RRs. Cracking within grout. Dirty grout.
Wood Flooring					
Terrazzo Floor / Special Composition					
Finish Concrete - (sealed)					
Stair Finishes					
Special Flooring / Misc Raised Access Flooring					
Interior Wall Finishes			1		VCT & carpet floors, CMU & gyp bd wall finish, ACT on ceiling.
Interior Partition Construction			1		Painted CMU (original building) & painted gyp bd (1979 Addition)
Wall Studs at interior columns					Unknown condition
Glazed block & CMU corridor			1		Mostly CMU throughout original building
Gypsum board at interior column furrings					within1979 Addition
Tape, Bed, Texture, & Paint interior column furrings					within1979 Addition
Studs insulation at interior face of exterior wall					Unknown condition
Gypsum board at interior face of exterior wall					within 1979 Addition
Tape, Bed, Texture, & Paint interior face of exterior wall					within 1979 Addition
- <u> </u>					

EXISTING INTERIOR FINISHES ASSESSMENT FORM

1= Excellent

2= Good

3= Fair 5= Failure 4= Poor

		1	-	
	Maintenance Cycle	Condition	Special Notes	
	Schedule	or	Or Observations	
Interior Balcony Railings	Years	Quality	Observations	
Wall Surface Finishes & Veneers		┪	Mostly painted CMU or brick. Elec. conduits on face of brick/CMU	П
Demountable / Folding / Office Partitions		 		<u>. </u>
Interior Louvers / Soundproofing / Misc.		+++		
Interior Wall Base & Trim		 		
			Openings in walls closed with brick/boarded up or patched w/CMI	11.1
Misc. Finishes			Mostly wood w/plastic laminate(PLAM) and is chipping or cracked	
Millwork Cabinets			iviosity wood w/plastic laminate(PLAW) and is chipping of cracked	u.
Display Cases			Manager and Control of the Control o	
Marker Boards			Masonite used for dry erase on top of old chalkboard	
Building Directory				
Corner Guards				
Lockers				
Mail Boxes				
Interior Signage / Graphics -ADA Graphics			Classroom & public RR signage. No direction signage	
Base Building Graphics & Signage				
Interior Finish Graphics & Signage				
A/V Equipment				
A/V Projection Screens			Using white boards as screen	
Interior Window Blinds			Most blinds are bent.	
Loading Dock Equipment			1	
Digital clocks			1	
Wireless access				
Conveying Systems			No conveying systems	
Freight Elevators			-	-
Cab Finishes			-	-
Passenger Elevators			1	
Cab Finishes			-	
Dumbwaiters / Lifts				
overall Restroom Condition & Finishes			Student restrooms in fair condition, not accessible.	-
Restroom Walls	T		Tiled floor to ceiling in public RR, exposed CMU in student RR	
Restroom Ceilings		- - - -	Mostly acoustic ceiling tile(ACT) in fair condition	
Restroom Fixtures		 		
Toilet Partitions		 	Plastic partitions in public RR, Glazed brick partition in student RF	R
Toilet Accessories		╅╬┼┼	Student restroom accessories in fair condition	
ADA accessibility	_	- 	Public restrooms are accessible, student restrooms are not.	
, i.e., i. dococommity		- 	- ability restriction are accessible, stadent restricting are not.	
ood Service Areas			Contains both functional & outdated equipment. Showing wear.	
Ood Service Areas			Contains both functional & outdated equipment. Showing wear.	

EXISTING INTERIOR FINISHES ASSESSMENT FORM

1= Excellent 2= Good 3= Fair 4= Poor

5= Failure

	Maintenance Cycle	С	onditi	ion		Special Notes
	Schedule		or			or
	Years	(Quali	ty		Observations
Equipment						Equipment is functional and in fair/good condition.
Serving lines						Components are outdated and no water service is provided.
Dish return area						Functional but aged & showing wear.
Dry storage pantry						Addition with cooler, exposed wiring
Food freezer and refrigerator						No walk-in freezer. Cooler is aged & showing wear.
Exhaust Hood						Fully functional
Flooring material and base						Tile flooring. Aged & showing wear.
Ceiling material						ACT. Aged & showing wear.
Wall Material and finish						Painted CMU/brick and glazed brick. Aged & showing wear.
Staff restroom						Not ADA code compliant.
Separate Locker room						Not present.
Food Service Office						Not present. Desk located in Kitchen/prep space.
Interior Doors & Hardware						Wood doors/frames and hollow metal frames. HW not compliant.
Interior Storefront / Glazed Walls / Borrow Lites						·
Interior Storefront / Entry Doors						Exposed wiring at entry storefront
Interior Doors (including frames)						wood & laminate doors. Wood & hollow metal frames.
Interior Overhead / Rolling Doors & Grilles						
Special Doors						
Interior Hardware						Not accessible
Interior Door Panic Hardware						
Interior Wall Base & Trim / Cabinets / Misc. Finishes						Mostly intact with some wear/chipping
terior ADA Compliance & Accessibility						Water fntain, classroom sinks/RR, most door hardwarenot ADA
Restrooms - Fixtures & Accessories						Student restrooms are not accessible.
Drinking Fountains						Not accessible
Interior Ramps						
Interior Signage						Door number signage with braille. Public RR has accessible signage.
Interior Doors and Hardware						Most door hardware is not accessible
Millwork/Fixed Workspaces						Millwork at accessible height, sinks don't have clear space below
Other?						
CM Materials						ACM present.
Presence of ACM Materials suspected?						
uilding Code Requirements						Unknown building code used.
Building code requirements met?						Unknown at this time
Energy code requirements met?						Unknown at this time.
Fire code requirements met?						No sprinklers.
		-				

EXISTING INTERIOR FINISHES ASSESSME	ENT FORI	M									
			1= Excellent				2= G	Good			
			3= Fair				4= P	Poor			
				5= Failure							
_											
	Maintenance Cycle		Co	onditio	n			Special Notes			
	Schedule	or		or				or			
	Years	Qu		Quality		,		Observations			
Average Interior Grade:							4				



401 N. GULF BLVD. FREEPORT, TX 77541

PROJECT INFORMATION

HVAC Unit Brand/Models: Unknown at this time.

Current Design Capacity: Unknown at this time.
Current Load: Unknown at this time.



	General Notes:							
Mechanical Systems								
Warranty	Unknown at this time.							
	Replace cooling tower & Central plant equipment							
Central Plant	(except Chiller)							
	Roof mtd. Fans appear to be original & recommend							
Roof Top Units	replacement							
Ductwork	AHUs and control valves in poor condition							
EMS	EMS (hybrid system) pneumatic part is failing & leaking.							
Electrical Systems								
Classroom Lighting	2x4 recessed, fair condition							
Corridor Lighting	2x4 recessed, fair condition							
Primary Power	Pole mounted transformers provided							
	Replace eqpmt. Replacement parts more expensive							
Panels	than new gear.							
Clock/Bell/ PA	Fair condition							
Plumbing Systems								
	Replace galvanized pipe with copper. Some corrosion @							
Main Water Supply	existing							
Drinking fountains	Not compliant.							
	Upgrade will be req'd if major work occurs within							
Toilet Fixtures	building							
Lavatory Fixtures	Not compliant. Upgrade will be req'd if major work							
Life Safety Systems								
Fire Sprinkler	Building is not sprinklered.							
Fire Extinguishers	No fire extinguishers.							
Fire Alarm	Fair condition.							
Technology								
Power/data	Adequate teacher/student computer drops							
Wireless	Yes.							

MEP SYSTEMS ASSESSMENT FORM

5= Failure Maintenance Cycle Condition Special Notes Schedule Quality Observations Years MPE&FP Systems 2 3 4 **HVAC** Replace cooling tower & Central plant equipment (except Chiller) Central Plant (including chillers, pumps, piping, valves, controls, & risers) Roof mtd. Fans appear to be original & recommend replacement Roof Mounted HVAC equipment (OA units, exhaust/stair press fans, etc.) AHUs and control valves in poor condition Main vertical trunk ducts through roof & floors (including rated chases) Recommend cleaning of ductwork interior Main horizontal trunk duct Perimeter zone low pressure ductwork & diffusers (T-bar slots) VAV dampers connected to hybrid DDC system Interior zone Variable Air Volume Boxes Interior zone low pressure ductwork & diffusers Ceiling mounted return air grilles No sound treatment for return air openings bet. Mech Rm & Class Rm Return air silencers at main return air intake No fire dampers observed All necessary fire dampers and smoke detectors as required by code Not all "exhaust" were running & is locally controlled by wall switch All restroom exhaust fans, ductwork, and electrical connections Electrical connections to all roof mounted equipment Corrosion visible Electrical connections to all Central Plant equipment DDC Control points for all roof mounted equipment П DDC Control points for all internal base building mounted equipment DDC Control points for all internal tenant building mounted equipment DDC control points for all VAV's Working but out of date components. Structure trim and curbing for roof mounted equipment EMS (hybrid system) pneumatic part is failing & leaking. **Energy Management System** HVAC system must meet NC-35 for noise criteria in occupied spaces Wall mounted thermostats Warranties still in effect Unknown at this time. Plumbing Main domestic water supply Replace galvanized pipe with copper. Some corrosion @ existing Units near end of life cycle. Recommend replacement Water heater systems (including piping & install) Cast iron visible, fair condition. Recommend videoing piping under bldg Sanitary waste water lines All condensate piping and drainage Part of bldg has PVC piping in open plenum. add'l drainage reg'd Building roof drainage piping Upgrade will be reg'd if major work occurs within building Toilet Fixtures - Condition and Type Upgrade will be req'd if major work occurs within building Flush Valves - Condition and type Not compliant. Upgrade will be reg'd if major work occurs within bldg. Lavatories - Condition and Type Upgrade will be reg'd if major work occurs within building Faucets - Condition and Type Not compliant. Electrical Water coolers - Condition and Type/ ADA

2= Good

4= Poor

1= Excellent 3= Fair

MEP SYSTEMS ASSESSMENT FORM

1= Excellent 2= Good 3= Fair 4= Poor 5= Failure

	Maintenance Cycle	Co	nditio	n .	1	Special Notes
	Schedule	CO	or) I I		or
	Years	Q	uality	,		Observations
Electrical	1					
Primary Service & Equipment						Pole mounted transformers provided
Power company transformer						
Main building switchgear including breakers			可			
Distribution Feeders						N/A
Panels (HVAC, Lighting, & power)			T			Replace eqpmt. Replacement parts more expensive than new gear.
Classroom lighting and type						2x4 recessed, fair condition
Corridor lighting and type			σ			2x4 recessed, fair condition
Light fixture Feeders						
Wall Switches						
Receptacles						
Equipment Connections						
Electric Heating						
Clocks/Bells/PA Systems						Fair condition
Telephone/Data Outlets						
UPS Systems						No emergency generator on site.
ife Safety Systems						
Sprinkler Main Riser						Building is not sprinklered.
General Building Wet Pipe System (per code)						
Sprinkler Heads - Condition and type						
Base Building Fire Alarm System (fully addressable)						Fair condition.
All Data Points & associated wiring						
Fire Alarm Annunciation Panel						No annunciation panel.
Horn Strobes & wiring						
Fire Alarm Pulls			可			
Emergency Lighting						Battery pack Itng installed randomly. Install generator & emerg. Ltng.
Exit Signage			可			Recommend upgrade w/ installation of emergency ltng system
Fire Extinguisher cabinets per code						No cabinets.
Fire Extinguishers						No fire extinguishers.

MEP SYSTEMS ASSESSMENT FORM						
		3=	: Excel : Fair : Failur			2= Good 4= Poor
	Maintenance Cycle Schedule Years		Condition or Qualit			Special Notes or Observations
Technology Systems and Equipment		_	Ш	_		
Teacher computer drops Student computer drops		\mp	<u> </u>		E	Adequate teacher/student computer drops
Wi FI Computer laboratories				0		Yes. 2 computer labs. Inadequate space.
Smart board Projectors						
MDF rooms IDF Rooms						
Average MEP Grade:						3





















































































SCHOOL REFERENCE 1











SCHOOL REFERENCE 1











SCHOOL REFERENCE 1



